



STEPS TO FOLLOW:

- ✓ Check if equipment is with analog or pulsed output.
- ✓ Unplug the controller from power supply.
- ✓ Connect to power supply again keeping pressed the keys  and .
- ✓ It will appear one of the following screens:



- ✓ By means of keys  and  change to "YES" or "NO".

Select "NO" when the **controller** is with **pulsed output**.



Select "YES" when the **controller** is with **analog output**.



Press key  to confirm.

- ✓ Then it will appear the screen:



Press key  to confirm.

- ✓ The process will be finished, and it should appear the consultation screen:



The equipment can be programmed again.

Sistemes Electrònics Progrés, S.A.

Polígon Industrial, C/ de la Coma, 2
25243 El Palau d'Anglesola | Lleida | España
Tel. 973 32 04 29 | info@progres.es
www.progres.es